

Report ID: 18,489,845 Version: 2 Created: 06 Sep 2018

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	EZA507	Reg Expiry:	21 Oct 2018	Engine			L
WoF Expiry:	30 Apr 2019	Odometer:	96,191 Kms	Good No:	18489845	Oil level	~		
VIN:	KMHBT51DR9U90797	Next Service:	107,000kms	Service Histor		Smoke & fumes	~		
					,	Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	PT PT			Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	sc 6/6			The		Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint def C = crack				+		Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	SPSC PIC			AL-	ENR	Wheel bearings	v v		
SC = stone chips						Brakes	V		
W = significant scuffs S SC W S PT PT PT PT						Performance V			
		Note: son			blayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftvre	L
Windscreen stone chips Head unit faulty						Left front	· ·	.5	mm
						Right front			mm
						Left rear		4	mm
Canalitian	- Dunin - De du la s		_			Right rear		4	mm
Conditions During Body Inspection: Dry						Spare	ů ř		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	j					Suspension performance	~		
						Steering performance	v v		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Electrical / Accessories	~		
	Average					Head lights			T
Seats							~		
Carpets	Average					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
General (Comments					Window winder FR	~		
Drive belt r						Window winder RL	~		
	/					Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)		~	<u> </u>
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism	Constant				Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	or cam belt keplac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Jason Law Date: 06 Sep 2018									
I have read and understood this condition guide. Name:									