

Report ID: 18,490,715 Version: 1 Created: 01 Sep 2018

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback	][		Pass	Fail	N/A	
Year:	2,008	Registration:	ESN214	<b>Reg Expiry:</b>	23 Oct 2018		Engine				
WoF Expiry:	25 Oct 2018	Odometer:	103,211 Kms	Good No:	18490715		Oil level	~			
VIN:	KMHBT51DR9U85819 <sup>,</sup>	Next Service:	110,000kms	Service Histor	<b>y:</b> Yes		Smoke & fumes	~			
Neter This we						1	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
	ical inspection phot to	purchase and t	ins can be analiged to		indige.	l	Coolant condition	~			
N		$\sim$	S* SD	S	S D	][	Performance	~			
<b>Key:</b> S = scratch		$\overline{(0)}$		5(O)-			Radiator / Hoses (visual)	>			
							Transmission				
R = rust SC 98							Operation	>			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent * = decals SDSC DD							CV joints	~			
* = decals SDSC SD							Wheel bearings	~			
W = significant scuffs							Brakes				
	SC S	$\sim$	S PT * PT	S	S D R		Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	~			
Left tail light damage							Tyres (lowest observed tread depth of tyres)				
							Left front		3	mm	
							Right front	3	.5	mm	
						]	Left rear	!	5	mm	
Conditions During Body Inspection: Dry							Right rear 5			mm	
						i	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension		1	1	
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
Interior Comments						1	Operation	~			
Interior Comments Good							Electrical / Accessories				
Seats	Good						Head lights	~			
Carpets	Good						Tail lights	~			
	Cood						Indicators	~			
Panels	Good						Dashboard warning lights	~			
Dashboa	Good Good						Wipers (front & rear)	~		<u> </u>	
						]	Window winder FL	~		<u> </u>	
Concret	Commonts					ון	Window winder FR	~			
	<u>Comments</u>						Window winder RL	~		-	
							Window winder RR	~		<u> </u>	
							Rear view mirrors	~		<u> </u>	
							Radio (basic test only)	~		<u> </u>	
							CD (basic test only)	~			
						ļ	Number of keys	3	1		
Road Conditions During Test Drive: Dry							Central locking	~		<u> </u>	
Engine Timing Mechanicment of the transmission						Ī	Remote locking	~		<u> </u>	
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 95,991							Sat. Nav. (basic test only)			~	
	oi Cam Beit Replac	ement: Y	es	Kms: 95	5,991		Reversing camera			~	
Inspected by: Ca Thach Date: 01 Sep 2018											

I have read and understood this condition guide.

Name: .....

Signature: .....