

Report ID: 18,490,770 Version: 2 19 Nov 2018 Created:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2003	Registration:	EQA393	Reg Expiry:	11 Aug 2019	Engine			
WoF Expiry:	16 Sep 2018	Odometer:	263,826 Kms	Good No:	18490770	Oil level	~		
VIN:	7A8GF0B0707003020	Next Service:	267000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and th	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	SC		S SC SC		S D	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			210		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	S P SC				2416	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan	SC		SC			Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4 mm		mm
						Right front	6 mn		mm
						Left rear	4	ŀ	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock ab						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, passenger	s side cracked ,				Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Centra							~		
, ,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 19 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: