

Basic Vehicle Condition Guide

Report ID: 18,491,121


Version: 3

Created: 09 Sep 2018

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2,008 Registration: Reg Expiry: **ESN223** 23 Oct 2018 WoF Expiry: **Odometer: Good No:** 18491121 02 Nov 2018 86,811 Kms VIN: KMHBT51DR9U85778 **Next Service: Service History:** 95,000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front wiper blades need replacement Mirror switch not working up and down

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Bonnet hinges tight

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Good | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

Engine vibration, noise. RPM needs attention Noise from dashboard while applying brake

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Inspected by: Mathew Varghese Date: 09 Sep 2018

Name:

Kms:

| | Pass | Fail | N/A | |
|--|-----------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | ~ | | | |
| Noise | | ~ | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 5 | mm | |
| Right front | | 5 | mm | |
| Left rear | 4 | 4 | mm | |
| Right rear | 3 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\triangle \) | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | | ~ | | |
| Window winder FL | ~ | | | |
| Window winder FR | V | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | | ~ | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| | | | | |

Signature: