

Report ID: 18,491,611 Version: 6 13 Mar 2019 Created:

Make:NissanModel:PathfinderBody Style:SUVEngineYear:2007Registration:HAN796Reg Expiry:29 Mar 2019EngineWoF Expiry:13 Mar 2020Odometer:227,809 KmsGood No:18491611Oil levelVIN:VSKJVWR51A0232735Next Service:230,000Service History:NoSmoke & fumes	Pass	Fail	N/A
WoF Expiry: 13 Mar 2020 Odometer: 227,809 Kms Good No: 18491611 Oil level	~		
	· ·		
Performance			
Note: This report is not a warranty	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System	•		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	~		
Porformanco	- V		
Key:			
S = scratch			
	~		
	~		
PT = paint defect C = crack			~
P = pin dent CV joints	~		
* = decals SP QQ Wheel bearings	- V		
SC = stone chips	V		
W = significant scuffs S Performance	~		
Note: come defecte 8 blemiches may not be displayed in the diagram	- V - V		
Body inspection Comments	-	hoftur	
LH tail lamp cracked	read dept		
		7	mm
Right front		7	mm
Left rear		7	mm
Conditions During Body Inspection: Wet			mm
Under Carriage & Under Bonnet Inspection Comments Suspension	Spare Yes Yes		
Steering performance	 ✓ 		
Shock absorbers	~		
Air Conditioning / Hea			
Interior Comments			
Average			
Seats head lights	~		
Carpets Average Tail lights		~	
Average Indicators	~		
Panels Dashboard warning in			
Dashboard Good Wipers (front & rear)	~	_	
Window winder FL	~		
General Comments Window winder FR Window winder RI	~		
Driver's seat adjusting switch knobs missing	~		
Window master switch not working,	~		
CD not working Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)		~	
Number of keys	1		
Road Conditions During Test Drive: Wet Central locking	~	<u> </u>	
Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test on	y)		~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera			~
Inspected by: Mathew Varghese Date: 13 Mathew	r 2010		
Inspected by, Mathew Valghese Date: 13 Ma	2017		

I have read and understood this condition guide.

Name:

Signature: