

Basic Vehicle Condition Guide

Report ID: 18,493,315


Version:

Created: 25 Sep 2018

Make: Model: **Body Style:** Utility Ford Ranger Year: Registration: HPP151 **Reg Expiry:** 2014 20 Nov 2018 **WoF Expiry: Odometer: Good No:** 09 Aug 2019 156,420 Kms 18493315 VIN: **Next Service: Service History:** MNAUMFF50EW28462 166,000kms No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Paint worn on top edge of right side sill, inside drivers door. 4 x small stone cracks in front windscreen, one in drivers viewing area that would need fixed for a w.o.f. Chrome coating on front grille is lifting off. Missing left rear mud flap. Small dent in right side sill, under drivers door.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Screw holes in left side of centre console. 2 x screw holes in right top corner of dashboard. Right front headlight not working on low beam.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Date: 03 Sep 2018 Jason Young

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	\(\triangle \)			
Radiator / Hoses (visual)	~			
Transmission		1		
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	5	.0	mm	
Right front	6	.4	mm	
Left rear	5.2		mm	
Right rear	5.5		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	~			
Shock absorbers 🗸				
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights				
Tail lights	•			
Indicators	-			
Dashboard warning lights Wipers (front & rear)	<i>V</i>			
Window winder FL				
Window winder FR Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Window winder RL				
Window winder RR	\(\times \)			
Rear view mirrors	•			
Radio (basic test only)	~			
CD (basic test only)	V			
Number of keys				
Central locking	2			
Remote locking	<i>V</i>			
Sat. Nav. (basic test only)			1	
Reversing camera			V	
L	l			

Signature: