

Basic Vehicle Condition Guide

Report ID: 18,494,438


Version: 2

Created: 21 Sep 2018

Make: Model: Hyundai **Body Style:** Wagon Tucson Year: 2008 Registration: EKQ975 Reg Expiry: 01 Jul 2019 **WoF Expiry: Odometer:** 10 Apr 2019 **Good No:** 18494438 130,427 Kms VIN: KMHJN81VR8U822642 **Next Service:** 139,000kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>	
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Good 2WD SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 04 Sep 2018

Name:

Fail N/A
~
f tyres)
mm
mm
mm
mm
Yes

Signature: