

Basic Vehicle Condition Guide

Report ID: 18,495,073


Version:

Created: 11 Oct 2018

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2013 Registration: HPW104 Reg Expiry: 20 Aug 2019 **WoF Expiry: Odometer:** 26 Jun 2019 **Good No:** 18495073 134,568 Kms VIN: KL3CD265JCB065383 **Next Service:** Service History: 142,000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left front head light low beam out

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|----------------------------|--|--|
| Seats | drivers seat rip rest good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

11 Oct 2018 Inspected by: lan Dunn Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|---|---------|----------|
| Engine | | • | |
| Oil level | ~ | | |
| Smoke & fumes | VVV | | |
| Performance | / | | |
| Noise | ~ | | |
| Cooling System | | • | • |
| Coolant condition | ~ | | |
| Performance | \(\times \) | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ' | | |
| CV joints | \(\times \) | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | > | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | es) |
| Left front | 4 | .4 | mm |
| Right front | 5.3 | | mm |
| Left rear | 5.3 | | mm |
| Right rear | 4.2 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ' | | |
| Steering performance | ' | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | | ~ | |
| Tail lights | ~ | | |
| Indicators | / | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | V V V V V | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ' | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | / | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ' |
| Reversing camera | • | | |

Signature: