

Report ID: 18,495,324 Version: 1 Created: 06 Sep 2018

Make: M	litsubishi	Model:	Airtrek	Body Style:	SUV		Pass	Fail	N/A
Year: 2,	,003	Registration:	FST823	Reg Expiry:	19 Feb 2019	Engine	1		1
· · · · ·	6 Aug 2019	Odometer:	202,624 Kms	Good No:	18495324	Oil level	~		
VIN: 7/	AT0CJ3FX10200457	Next Service:	212,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	rt is not a warranty	pration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanica	al inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	SW SW	-01-	<u>S D</u>	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack					S SC	Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts SC SP SP						Performance	~		
Body Inspec	ction Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Stone chips in windscreen.						Tyres (lowest observed tread depth of tyres)			
					Left front 4.4			mm	
						Right front	3.	.6	mm
						Left rear	4	.2	mm
Conditions During Body Inspection: Dry						Right rear	4.2		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Split inner left	side cv boot.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpots	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboard	Good				Wipers (front & rear)	~			
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			٢
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanismu en el lu						Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 192,120						Sat. Nav. (basic test only)			~
Evidence of	Cam Belt Replace	ement: Y	es	Kms: 19	92,120	Reversing camera	~		
Inspected by: Jason Young Date: 04 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: