

Basic Vehicle Condition Guide

Report ID: 18,496,310

Version:


Created: 04 Sep 2018

Make: Model: **Body Style:** Audi Hatchback

Year: 2,005 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 29 Aug 2019 18496310 52,007 Kms **Service History:** VIN: WAUZZZ8P35A07314 **Next Service:** 61,985kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Commen	<u>ts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

(1eneral	Comments

Good A3 wagon.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

inspected by:	Daryii Hmms	Date: 04 Sep 2	04 Sep 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission		!	-
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	· ·		
Brakes			
Performance	·/		
Hand Brake	1		
Tyres (lowest observed treat	d dopth	of tur)
Left front	<u> </u>		
		7	mm
Right front		7	mm
Left rear		7	mm
Right rear	-	7	mm
Spare		Yes	
Suspension			1
Suspension performance	-		
Steering performance	\(\times \)		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	v v		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		1
Central locking	·		
Remote locking	·		
Sat. Nav. (basic test only)	+		_
Reversing camera			<i>y</i>
versing carriera			

I have read and understood this condition guide.

Name:

Signature: