

Report ID: 18,496,807 Version: 1 Created: 05 Sep 2018

Make:	Mazda	Model:	Bt-50	Body Style:	Utility	] [	Pass	Fail	N/A
Year:	2,014	<b>Registration:</b>	HPC846	<b>Reg Expiry:</b>	30 Oct 2018	Engine			•
WoF Expiry:	04 Jul 2019	Odometer:	202,318 Kms	Good No:	18496807	Oil level	~		
VIN:	MM0UP0YF100220904	Next Service:	206000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S W				S D	Performance	~		
Key:		-0	SD.			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust PT = paint defect						Operation		~	
						Noise	~		
C = crack					R SC	Clutch			~
P = pin dent						CV joints	~		
* = decals SC 999 D						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S D S D S S W						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Left rear taillight						Tyres (lowest observed tread depth of tyres)			
					Left front 8 r			mm	
						Right front		8 mm	
						Left rear		8 mm	
Conditions During Body Inspection: Dry						Right rear	8 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody	oxidisation					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	it holes				Head lights	~		
	Average					Tail lights		~	
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Harsh gear changes						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	/ 1	
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 05 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....