

Report ID: 18,497,051 Version: 2 Created: 05 Sep 2018

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,013	Registration:		Reg Expiry:		Engine				
WoF Expiry:		Odometer:	83,158 Kms	Good No:	18497051	Oil level	~			
VIN:	7AT0C144X18122794	Next Service:	93,100kms	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Parts have not	boon dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	iical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust				715		Operation	~			
PT = paint defe	ect NP	FI		$\left( \left  \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HE				7414	CV joints	~			
* = decals	MA					Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significant						Performance	~			
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments Factory repair kit instead of spare wheel.						Tyres (lowest observed trea	Tyres (lowest observed tread depth of tyres)			
						Left front	Left front 8.0 m			
						Right front	8	.0	mm	
						Left rear		.0	mm	
Conditions During Body Inspection: Dry						Right rear	8.0		mm	
						Spare	No			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Tidy .						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	ira					Window winder FL	~			
	-					Window winder FR	~			
General Comments						Window winder RL	~			
Nice diesel	turdo SUV.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		-	
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanisms						Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecte	d by: Daryll Timms					Date: 04 Sep 20	)18			

I have read and understood this condition guide.

Name: .....

Signature: .....