

Basic Vehicle Condition Guide

Report ID: 18,497,079


Version:

Created: 04 Sep 2018

Make: Model: Honda Stepwagon **Body Style:** SUV Year: 2,007 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 30 Aug 2019 18497079 81,045 Kms VIN: 7AT08G87X18220509 **Next Service:** 91,041kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Good 8 seater people mover.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 04 Sep 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	V		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front	7		mm
Left rear	7		mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater		ļ	
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	•		
Remote locking	·		
Sat. Nav. (basic test only)			./
Reversing camera			
neversing curriera			

Signature: