


<b>Make:</b>	Toyota	<b>Model:</b>	Hilux	<b>Body Style:</b>	Utility
<b>Year:</b>	2014	<b>Registration:</b>	HPF924	<b>Reg Expiry:</b>	01 Aug 2019
<b>WoF Expiry:</b>	26 Jul 2019	<b>Odometer:</b>	164,973 Kms	<b>Good No:</b>	18497371
<b>VIN:</b>	MR0EZ12G204158197	<b>Next Service:</b>	168000	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments**
**Interior Comments**

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

**General Comments**

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✗		
Smoke & fumes	✗		
Performance	✗		
Noise	✗		
<b>Cooling System</b>			
Coolant condition	✗		
Performance	✗		
Radiator / Hoses (visual)	✗		
<b>Transmission</b>			
Operation	✗		
Noise	✗		
Clutch	✗		
CV joints			✗
Wheel bearings	✗		
<b>Brakes</b>			
Performance	✗		
Hand Brake	✗		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	7	mm	
Right front	7	mm	
Left rear	7	mm	
Right rear	7	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✗		
Steering performance	✗		
Shock absorbers	✗		
<b>Air Conditioning / Heater</b>			
Operation	✗		
<b>Electrical / Accessories</b>			
Head lights	✗		
Tail lights	✗		
Indicators	✗		
Dashboard warning lights	✗		
Wipers (front & rear)	✗		
Window winder FL	✗		
Window winder FR	✗		
Window winder RL	✗		
Window winder RR	✗		
Rear view mirrors	✗		
Radio (basic test only)	✗		
CD (basic test only)	✗		
Number of keys	1		
Central locking	✗		
Remote locking	✗		
Sat. Nav. (basic test only)			✗
Reversing camera			✗

Inspected by: Bobby Zhong

Date: 08 Nov 2018

I have read and understood this condition guide.

Name: .....

Signature: .....