Turners


Basic Vehicle Condition Guide

Report ID: 18,497,521
Version: 1
Created: 09 Sep 2018

Make:	Hyundai	**Model:**	Getz	**Body Style:**	Hatchback
Year:	2,009	**Registration:**	EUW310	**Reg Expiry:**	19 Oct 2018
WoF Expiry:	14 Feb 2019	**Odometer:**	93,930 Kms	**Good No:**	18497521
VIN:	KMHBT51DR9U89214	**Next Service:**	104,799	**Service History:**	Yes

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Bonnet hinges tight

Interior Comments

Seats	Good
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Rattling from rear
AC on indication not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	3 mm		
Right front	4 mm		
Left rear	4 mm		
Right rear	4 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Mathew Varghese Date: 09 Sep 2018

I have read and understood this condition guide. Name: ..... Signature: .....