

Basic Vehicle Condition Guide

Report ID: 18,498,253


Version: 2

Created: 30 Nov 2018

Make: Model: Toyota Landcruiser Prado **Body Style:** SUV Year: 2004 Registration: CHH788 Reg Expiry: 31 Jan 2019 WoF Expiry: **Odometer:** 17 Sep 2019 209,905 Kms **Good No:** 18498253 VIN: JTEBU25J200048668 **Next Service:** 220000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	drivers seat worn		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan

Name:

Create	u. J	J NOV 2	2016	
	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	~			
Noise	~			
Cooling System	•			
Coolant condition	~			
Performance	<i>V</i>			
Radiator / Hoses (visual)	~			
Transmission	•		•	
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	3.0		mm	
Right front	3.0		mm	
Left rear	4.0		mm	
Right rear	4.0		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater			1	
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V V V V V V V V			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	·			
Window winder RR	<i>'</i>			
Rear view mirrors	<i>'</i>			
Radio (basic test only)				
CD (basic test only)	~			
Number of keys	1			
Central locking	•			
Remote locking	1			
<u> </u>			.,	
Sat. Nav. (basic test only) Reversing camera			.,	
neversing camera				

12 Sep 2018

Signature:

Date: