

# **Basic Vehicle Condition Guide**

Report ID: 18,498,351

Pass

Version: 1

Engine

Created: 04 Sep 2018


Fail

N/A

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: Registration: EUW308 Reg Expiry: 19 Oct 2018 2,009 **WoF Expiry: Odometer:** 13 Feb 2019 **Good No:** 18498351 100,963 Kms VIN: KMHBT51DR9U88325 **Next Service: Service History:** 108,832kms Yes

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Windscreen stone chips Front wipers need replacement vote. some defects & bieffishes may not be displayed in the diagraf

Conditions During Body Inspection: Dry

### **Under Carriage & Under Bonnet Inspection Comments**

Under bonnet surface rust

Interior Comments			
Seats	Good		
Carpets	Average		
Panels	Good		
Dashboard	Good		

## **General Comments**

Inspected by:

Excessive vibration when in gear

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Ca Thach

Evidence of Cam Belt Replacement: No

Kms:

Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		!	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	(	5	mm
Right front	6		mm
Left rear	3.5		mm
Right rear	-		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\( \triangle \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	I.	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			V

I have read and understood this condition guide.

Name: .....

Signature: .....

04 Sep 2018

1

Reversing camera