

Basic Vehicle Condition Guide

Report ID: 18,498,708

Version:


Created: 12 Sep 2018

Make: Model: Noah **Body Style:** SUV Toyota Year: 2,005 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 03 Sep 2019 96,485 Kms 18498708

VIN: **Next Service:** 7AT0H64NX18437287 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

09 Sep 2018 Inspected by: Xinghui Lin Date:

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	V			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	3	.5	mm	
Right front	3	.5	mm	
Left rear	4.0		mm	
Right rear	4.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors				
Radio (basic test only)	'			
CD (basic test only)	~			
Number of keys	1			
Central locking	'			
Remote locking	'		<u> </u>	
Sat. Nav. (basic test only)			'	
Reversing camera			'	

Signature: