

Basic Vehicle Condition Guide

Report ID: 18,499,609


Version: 2

Created: 10 Sep 2018

Make: Model: Mazda **Body Style:** Sedan Atenza Year: 2,003 Registration: FLD555 Reg Expiry: 19 Nov 2018 WoF Expiry: **Odometer:** 21 May 2019 **Good No:** 18499609 185,140 Kms VIN: 7AT0C139X10109849 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

FL tyre sidewall needs attention LH tail lamp lens cracked, moisture inside Front bumper valance broken

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

General Comments

Rubbing noise from steering canopy FR fog light not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 10 Sep 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	v		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	_		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front			mm
Right front	5		mm
Left rear	3		mm
Right rear	4		mm
Spare		Yes	
Suspension		103	
Suspension performance	V		
Steering performance	<i>\'\'</i>		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	·		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights			
Wipers (front & rear)	V		
Window winder FL	<i>v</i>		
Window winder FR	~		
Window winder RL			
Window winder RR	V		
	V		
Rear view mirrors			
Radio (basic test only)	/		
CD (basic test only)	·		
Number of keys	1		
Central locking	<i>'</i>		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	1	1	· •

Signature: