

Report ID: 18,499,904 Version: 1 Created: 06 Sep 2018

Make:	Subaru	Model:	Forester	Body Style:	SUV		Pass	Fail	N/A
Year:	2,008	Registration:	EPP186	Reg Expiry:	19 Apr 2019	Engine		I	I
WoF Expiry:	20 Jul 2019	Odometer:	243,154 Kms	Good No:	18499904	Oil level	~		
VIN:	JF2SH9KK49G008273	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for one and miles as	Danta hava nat	heen discontined or	Noise	~		
diagnostic te	s a guide only. Considesting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	-		
a full mechai	nical inspection prior to	purchase and t	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S S		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent P = rust W D W						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HIG				ᅰЦ	CV joints	~		
* = decals	sc 916			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W D						Performance	~		
Nata como defecto 9 hierriches may not be displayed in the diagram						Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	-	of tyre	es)
Stone chips front screen. Left headlight not working on low beam.					Left front 7			mm	
						Right front		, 7	mm
						Left rear		, 1	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights		~	
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ard					Window winder FL	~		
					· · · · · · · · · · · · · · · · · · ·	Window winder FR	~		
General	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
									·
Inspected by: Brian Hill Date: 06 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....