

Report ID: 18,500,309


Version:

05 Sep 2018 Created:

| Make: | Hyundai | Model: | 140 | Body Style: | Wagon |
|-------------|------------------|---------------|-------------|-----------------|---------------|
| Year: | 2,014 | Registration: | HGM191 | Reg Expiry: | 30 Jan 2019 |
| WoF Expiry: | 31 Jan 2019 | Odometer: | 128,863 Kms | Good No: | 18500309 |
| VIN: | KMHLB81UMEU07987 | Next Service: | 128136 | Service History | /: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Dirty

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 05 Sep 2018 Inspected by: Stuart Melbourne

Name:

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|----------|
| Engine | | | 1 |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 5 | mm |
| Right front | | 5 | mm |
| Left rear | | 5 | mm |
| Right rear | | 5 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \(\times \) | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | ı |
| Central locking | ' | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ' |
| Reversing camera | | | ' |

Signature: