

Report ID: 18,500,332 Version: 1 Created: 05 Sep 2018

Make:	Lexus	Model:	ES300	Body Style:	Sedan		Pass	Fail	N/A
Year:	1,999	Registration:	ENC630	Reg Expiry:	21 Jul 2018	Engine	1	I	
WoF Expiry:	11 Feb 2018	Odometer:	196,228 Kms	Good No:	18500332	Oil level	~		
VIN:	7A8B0010708017247	Next Service:	174000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SD S	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S D SC S D C S D C						Operation			
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					S D	Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	SDSC 91			The second	ALC'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S D SC S D SC S S SC						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments RR tail light broken ,						Tyres (lowest observed tread depth of tyres)			es)
						Left front 2 mm			mm
						Right front		2	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	-		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	drivers su	n visor broken ,				Dashboard warning lights	~		
<u></u>	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	ł					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 10	3,000	Reversing camera			~
Inspected by: Donovan Matara Date: 05 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: