# Turners

# Basic Vehicle Condition Guide

| | | | |
|---|---|---|---|
| **Make:** | Holden | **Model:** | Rodeo 4X2 |
| **Year:** | 2004 | **Registration:** | CKC807 |
| **WoF Expiry:** | 17 Sep 2019 | **Odometer:** | 259,671 Kms |
| **VIN:** | MPATFR77H4H558399 | **Next Service:** | 270000 |

| | |
|---|---|
| **Body Style:** | Utility |
| **Reg Expiry:** | 28 Feb 2019 |
| **Good No:** | 18501810 |
| **Service History:** | No |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

SC · S D SC · S D SC · S D
S SC
D
SC
SC
S D SC
SC
S SC

Note: some defects & blemishes may not be displayed in the diagram

## Body Inspection Comments

Indicators missing from the front bumper ,back half of the ute is black ,

| Conditions During Body Inspection: | Dry |
|---|---|

## Under Carriage & Under Bonnet Inspection Comments

## Interior Comments

| | |
|---|---|
| Seats | drivers seat ripped , |
| Carpets | Average |
| Panels | Average |
| Dashboard | stereo missing , |

## General Comments

Stereo missing ,

| Road Conditions During Test Drive: | Dry |
|---|---|

| Engine Timing Mechanism: | Unknown |
|---|---|
| Evidence of Cam Belt Replacement: | Not Applicable | Kms: |

| | Pass | Fail | N/A |
|---|---|---|---|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | ✔ | | |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 5 | | mm |
| Right front | 5 | | mm |
| Left rear | 4 | | mm |
| Right rear | 4 | | mm |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | | ✔ | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | | | ✔ |
| CD (basic test only) | | | ✔ |
| Number of keys | 1 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | | | ✔ |

| Inspected by: | Donovan Matara | Date: | 08 Oct 2018 |
|---|---|---|---|

I have read and understood this condition guide.     Name: …………………………………………     Signature: …………………………………