

Report ID: 18,502,151 Version: 1 11 Sep 2018 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,017	Registration:	KUN713	Reg Expiry:	04 Dec 2018	Engine			
WoF Expiry:	05 Sep 2020	Odometer:	10,397 Kms	Good No:	18502151	Oil level	~		
VIN:	JM0BN547810177950	Next Service:	19700	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	D SC				SC	Performance	~		
Key:	LD SC IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust S SC S						Operation	~		
PT = paint def	ect NP				101/1	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals	sc 91					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			es)
					Left front 5 mm			mm	
						Right front		5	mm
						Left rear		, 1	mm
Conditions During Body Inspection: Wet						Right rear		1	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good cond	ition.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	· ·		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	• •		
Dashboa	rd Good					Window winder FL	· ·		
						Window winder FR	• •		
General C	<u>Comments</u>					Window winder RL	• •		
Drives well.						Window winder RR	~		
						Rear view mirrors	• •		
						Radio (basic test only)	· ·		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Wet						Central locking	2 V		
			Wet			Remote locking	• •		
Engine Timing Machanismu Turk Curk						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
	•	•							
Inspected by: Roger King Date: 11 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: