

Report ID: 18,502,360 Version: 2 Created: 03 Oct 2018

Make:	Holden	Model:	Barina	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	ERF511	Reg Expiry:	12 Nov 2018	Engine	1	I	L
WoF Expiry:	11 Aug 2019	Odometer:	136,402 Kms	Good No:	18502360	Oil level	~		
VIN:	KL3SA08619B318440	Next Service:	143938	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC D S						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance 🖌			
Note: come defects % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
No parcel tray						Left front	· ·	.0	mm
						Right front	-	.0	mm
						Left rear	-	.0	mm
Condition	s During Body Inc	anotion:	Deri			Right rear			mm
Conditions During Body Inspection: Dry						Right rear 5.0 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
Surface rust	:					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats	Seats Average					Head lights	~		
50005						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Fallels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>Gen</u> eral (<u>Comments</u>					Window winder RL	-		~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
						Central locking	1		
Road Conditions During Test Drive: Dry						Remote locking	<i>v</i> <i>v</i>		
Engine Timing Mechanism: Cambelt							-		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			v
						Reversing camera			~
Inspected by: Stuart Melbourne Date: 07 Sep 2018									
I have read and understood this condition guide. Name:									