

Report ID: 18,502,387 Version: 1 Created: 27 Sep 2018

Make:	Honda	Model:	Stream	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	JZD115	Reg Expiry:	03 Feb 2019	Engine	1		
WoF Expiry:	07 Sep 2018	Odometer:	74,015 Kms	Good No:	18502387	Oil level	~		
VIN:	7AT08GADX16105230	Next Service:	not known	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC		PT SC			Performance	~		
Key:	Bell	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	w AR			210		Operation	~		
PT = paint def	ect NP				10111	Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	PT dl				24116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan			SC			Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Stone chips front screen. Left front seat base trim panel broken						Tyres (lowest observed tread depth of tyres)			es)
					Left front 5		5	mm	
						Right front	e	5	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare Yes			
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compete	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	<		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	٢		
						Window winder RR	<		
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
Inspected by: Brian Hill Date: 27 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: