

Basic Vehicle Condition Guide

Report ID: 18,502,829

Version: 1

Created: 07 Sep 2018

Make: Subaru Model: Impreza Body Style: Hatchback


 Year:
 2,008
 Registration:
 Reg Expiry:

 WoF Expiry:
 06 Sep 2019
 Odometer:
 94,693 Kms
 Good No:
 18502829

 VIN:
 7AT0GF09X18007087
 Next Service:
 104,689kms
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Nice STi Impreza.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No.

No

Kms:

Name:

Inspected by:	Daryll Timms	Date:	07 Sep 2018

Pass	Fail	N/A
	•	•
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
d depth	of tyre	es)
I		mm
		mm
		mm
-		mm
~		
~		
~		
L	<u> </u>	I
~		
V		
_		
<u></u>		
<i>'</i>		
~		
./		
· ·		
1/		
2		
l		V
~		
	V V V V V V V depth	マ

Signature: