

Basic Vehicle Condition Guide

Report ID: 18,503,444


Version:

Created: 12 Sep 2018

Make: Model: Hilux **Body Style:** Utility Toyota Year: Registration: GMD985 Reg Expiry: 17 Mar 2019 2,012 WoF Expiry: **Odometer:** 17 Oct 2018 **Good No:** 18503444 121,577 Kms VIN: MR0DZ22G100022376 **Next Service: Service History:** 127000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stonechips on windscreen.

Damage to both ends of LH running board.

Has jack, no tools.

Inside mirror in glovebox.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Average condition.

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Roger King

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5		mm
Right front	5		mm
Left rear	2 1		mm
Right rear	2		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v v		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking			~

I have read and understood this condition guide.

Name:

Signature:

12 Sep 2018

Reversing camera