

Report ID: 18,503,601 Version: 1 Created: 17 Sep 2018

Make:	Hyundai	Model:	140	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015	Registration:	JFC786	Reg Expiry:	23 Sep 2019	Engine			·
WoF Expiry:	31 Jul 2019	Odometer:	79,789 Kms	Good No:	18503601	Oil level	~		
VIN:	KMHLB41DMFU06596	Next Service:	94,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S* S	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SPT SC S S						Operation	~		
R = rust PT = paint defe				\prod		Noise	· ·		
C = crack				+	SC	Clutch	•		~
P = pin dent					게비	CV joints	~		
* = decals	616			- NL	ELIP-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				ayea III the alagiant	Tyres (lowest observed tread	÷	oftyre	
					Left front 6 mm				
						Right front			mm
						Left rear	6		-
							3 mm		
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	iner inspectie	<u>eonnento</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Cancella						Window winder FR	~		ļ
General Comments Engine minor tapping noise						Window winder RL	~		ļ
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Mathew Varghese Date: 17 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: