

Report ID: 18,503,780 Version: 1 Created: 28 Sep 2018

Make:	Subaru	Model:	Impreza	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2003	Registration:	CFQ868	Reg Expiry:	18 Dec 2018	Engine	1	I	1	
WoF Expiry:	25 Jan 2019	Odometer:	191,250 Kms	Good No:	18503780	Oil level	~			
VIN:	7A8GF090704009860	Next Service:	196000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for any and mileage. Parts have not been dismantled or						Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~		1	
						Performance	~			
Key:	s w	-0	S S		S D	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation	~		1	
R = rust						Noise	~			
PT = paint defect C = crack						Clutch	~		+	
P = pin dent						CV joints	-		<u> </u>	
* = decals							~		<u> </u> !	
SC = stone chips						Wheel bearings	~			
W = significant scuffs S P W S S P W S						Brakes				
						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		<u> </u>	
Stone chips front screen. Front bumper loose. Right rear door chrome finishing.						Tyres (lowest observed tread depth of tyres)				
						Left front	Left front 3			
						Right front	3	3	mm	
						Left rear	7	.5	mm	
Conditions During Body Inspection: Dry						Right rear	7	.5	mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension	uspension			
Engine fluid	l leak.Rear diff left hand	CV boot broken				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	V			
	, Good					Wipers (front & rear)	V		1	
Dashboa	rd					Window winder FL	~		1	
	•					Window winder FR	~		1	
General Comments						Window winder RL	~		1	
Central locking not working with key.Remote not working.Drivers door mirror cover broken.						Window winder RR	V			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Drv						Central locking	· ·			
	uning resi		Dry			Remote locking		~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)		-	~	
-	of Cam Belt Replac		'es	Kms: 19	91,270	Reversing camera			v v	
	-1				.,_, ~					
Inspected by: Eddie Marsters Date: 28 Sep 2018										
I have read and understood this condition guide. Name:										