

Report ID: 18,503,952 Version: 1 Created: 13 Sep 2018

Make:	Mazda	Model:	Atenza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2003	Registration:	GES405	Reg Expiry:	28 Nov 2018	Engine			L
WoF Expiry:	17 Jul 2019	Odometer:	133,380 Kms	Good No:	18503952	Oil level	~		
VIN:	7AT0C139X11949629	Next Service:	135,370kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD SD	-0×	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S D SC			715	HIVS	Operation	~		
PT = paint defe		F I		$\left(\left \left(\right) \right\rangle \right)$	7014	Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				74116	CV joints	~		
* = decals	sc 916			Tool .	ED PT	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S D W		SW SW		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	2	2	mm	
						Right front	2	2	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	۲		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets	-					Indicators	~		
Panels	Average					Dashboard warning lights	<		
Dashboa	rd Average					Wipers (front & rear)	~		
	iu -					Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL	~		
Good wago	nı.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ning Machanism	T ''				Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 13 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: