


Report ID: 56,039

Version:

Created: 20 Sep 2018

 $\mathsf{m}\mathsf{m}$ mm

 $\mathsf{m}\mathsf{m}$



Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

I have read and understood this condition guide.

DM AUTOS

Inspected by:

	Central locking	~						
	Remote locking	~						
	Sat. Nav. (basic test only)		~					
Kms:	Reversing camera		V					
Date: 18 Sep 2018								
Name: Signature:								

M	lake:	Volkswagen	Model:	Passat	Body Style:	Wagon			Pass	Fail	1
Y	ear:	2010	Registration:	FKT590	Reg Expiry:	29 Jan 2019	Ш	Engine			
W	oF Expiry:	25 Sep 2019	Odometer:	128,265 Kms	Good No:	18504303	Ш	Oil level	~		
V	IN:	WVWZZZ3CZAE14565	Next Service:	137000	Service Histor	y: Yes	╝	Smoke & fumes	~		Γ
							7	Performance	~		
		oort is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	: been dismantled o		Noise	/		Ī
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System						
d	Tuli mechani	ical inspection prior to	purchase and ti	iis can be arranged to	r an additional (inarge.		Coolant condition	~		Ī
	_	S					٦	Performance	/		Γ
	(ey:	3	= (0)		2(0)=			Radiator / Hoses (visual)	~		
S = scratch D = dent					-	Transmission					
	= rust					IIII Is	J	Operation	~		Ī
ךכ	Γ = paint defe	ect NM				11111	٦.	Noise	/		Ī
C	= crack						┚	Clutch			
	= pin dent	HIP				24HF		CV joints	~		
	= decals	- Alk			7			Wheel bearings	~		Γ
SC = stone chips W = significant scuffs						Brakes					
vv	– sigiiiicani	Sculis				S	Ш	Performance	~		
	Rody Inst	ection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Ш	Hand Brake	~		Г
body inspection comments						Ш	Tyres (lowest observed tread	l depth	of tyre	s)	
							Ш	Left front	5.	.0	m
							Ш	Right front	3.	.0	m
_							┚╽	Left rear	- 3	3	m
	Condition	ns During Body Insp	oection:	Dry			٦	Right rear	- 3	3	m
		3		Diy			۱	Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments				Ш	Suspension			_			
							Ш	Suspension performance	~		
							Ш	Steering performance	~		Г
							Ш	Shock absorbers	~		Г
						Ш	Air Conditioning / Heater				
							7	Operation	~		Г
	Interior Comments						Ш	Electrical / Accessories			
	Seats	GOOD					Ш	Head lights	~		Г
	_	GOOD					Ш	Tail lights	~		
	Carpets						Ш	Indicators	~		Г
	Panels	GOOD					Ш	Dashboard warning lights	~		Г
		, GOOD					Ш	Wipers (front & rear)	~		
	Dashboa	rd Good					Ш	Window winder FL	~		Г
		•					۱	Window winder FR	~		
	General C	omments						Window winder RL	~		Г
								Window winder RR	~		Γ
								Rear view mirrors	~		
								Radio (basic test only)	~		Γ
								CD (basic test only)	~		
							$ oldsymbol{L}$	Number of keys	2		_
									i		