

Report ID: 18,504,700 Version: 1 Created: 26 Sep 2018

Make:	Citroen	Model:	C5	Body Style:	Wagon		Pass	Fail	N/A
Year:	2003	Registration:	BBM853	Reg Expiry:	02 Oct 2018	Engine			
WoF Expiry:	25 Nov 2018	Odometer:	119,123 Kms	Good No:	18504700	Oil level	~		
VIN:	VF7DEXFXF76360362	Next Service:	119,125 KIIS	Service Histor		Smoke & fumes	~		
	VI / DEXI XI / 0500502				. 110	Performance	~		-
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									1
						Coolant condition	~		
Key:	SC		S D S			Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
D = dent	Alt				HID IS	Transmission			1
R = rust	s sc			$1 \land$	SHIY	Operation	~		
PT = paint def	ect M					Noise	~		
C = crack P = pin dent						Clutch			~
* = decals	sc dk				Ella	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	SC W		SC S	W	S D	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Stonechips on windscreen. Tailgate not staying up. Sticker across bottom of tailgate is worn. RH piece of						Tyres (lowest observed tread depth of tyres)			
grille and two covers missing on front bumper. Lid in console not opening.						Left front	:	5	mm
						Right front	(5	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear		2	mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine has	oil seepage.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
	Average					Electrical / Accessories			1
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
<u> </u>	Average					Indicators	~		
Panels	Avelage					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
	ommonto					Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
Starter noisy when cold.						Window winder RR	~		<u> </u>
Drives ok.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
			10	11113.		Reversing camera			~
Inspected by: Roger King Date: 26 Sep 2018									
I have read and understood this condition guide. Name:									