

Report ID: 18,504,802 Version: 1 11 Sep 2018 Created:

Make:	Suzuki	Model:	Splash	Body Style: Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:	Spidsin	Reg Expiry:	Engine		-	
WoF Expiry:	31 Aug 2019	Odometer:	68,274 Kms	Good No: 18504802	Oil level	~		
VIN:	TSMEXB32S00287817	Next Service:		Service History: No	Smoke & fumes	~		
	151112/052500207017		70500		Performance	~		<u> </u>
	port is not a warranty				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition			
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch					Transmission			
D=dent					Operation	~		<u> </u>
R = rust					Noise	~		
PT = paint def C = crack	ect				Clutch	~		
P = pin dent	Ht	KI				~		~
* = decals	MIR				CV joints			
SC = stone chi	ips U				Wheel bearings	~		
W = significant scuffs					Brakes			
					Performance	~		
Body Ins	pection Comments	Note: son	ie defects & biemishe	s may not be displayed in the diagram	Hand Brake	~		Ļ
					Tyres (lowest observed tread depth of tyres)			
					Left front	7	7	mm
					Right front	7	7	mm
					Left rear	7	7	mm
Conditions During Body Inspection: Dry					Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	pare Yes		
Under Ca	arriage & Under Bor	nnet inspectio	on Comments		Suspension			
					Suspension performance	~		
					Steering performance	~		
					Shock absorbers	~		
					Air Conditioning / Heater			
					Operation	~		
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
Corret	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights	~		
	Good				Wipers (front & rear)	~		
Dashboa	ara				Window winder FL	~		
					Window winder FR	~		
General Comments					Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		L
Road Conditions During Test Drive: Dry					Central locking	~		
			у		Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing	Chain		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~
						I		
Inspecte	d by: John Lindsay				Date: 11 Sep 20	18		

I have read and understood this condition guide.

Name: