

Basic Vehicle Condition Guide

Report ID: 18,505,327


Version:

Created: 05 Oct 2018

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2014 Registration: HTT106 Reg Expiry: 20 Nov 2018 **WoF Expiry: Odometer:** 21 Nov 2018 **Good No:** 18505327 166,483 Kms VIN: KMHST81XSFU374434 **Next Service:** Service History: 175000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Damage to front bumper and stone guard

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 04 Oct 2018 Inspected by: Dion Mair

| | Pass | Fail | N/A | | |
|------------------------------|---------------------------------------|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 5 | .0 | mm | | |
| Right front | 5 | .0 | mm | | |
| Left rear | 4.0 | | mm | | |
| Right rear | 4.0 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | V V V V V V V V V V V V V V V V V V V | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | • | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature: