

Basic Vehicle Condition Guide

Report ID: 18,505,772


Version: 2

Created: 26 Oct 2018

Make: Model: Corolla **Body Style:** Hatchback Toyota Year: 2001 Registration: FUE323 Reg Expiry: 10 Jun 2019 **WoF Expiry: Odometer:** 04 Sep 2019 **Good No:** 18505772 187,856 Kms VIN: 7AT0H607X11000834 **Next Service: Service History:** 195,000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 12 Sep 2018

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	es)
8.3		mm
7.7		mm
7.9		mm
7.5		mm
	Yes	
~		
~		
~		
~		
	1	
~		
~		
~		
~		
~		
-		
-		
-		
•		
~		
	~	
	~	
2		
'		
'		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

Signature: