

Report ID: 18,505,861 Version: 1 11 Sep 2018 Created:

Make:	Peugeot	Model:	508	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,011	Registration:	FYN721	Reg Expiry:	30 Nov 2018	Engine	•	•	
WoF Expiry:	14 Nov 2018	Odometer:	73,609 Kms	Good No:	18505861	Oil level	~		
VIN:	VF38D4HLABL019398	Next Service:	72442	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-0×		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	r		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	V		
* = decals	- Alt					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W						Performance	~		
Bodylac	Dection Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			<u>د</u>
						Left front 4			mm
						Right front		1	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	-1	ľ							_ *
Inspected by: Stuart Melbourne Date: 11 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: