

Report ID: 18,507,188 Version: 2 07 Nov 2018 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback			Pass	Fail	N/A
Year:	2017	<b>Registration:</b>	KTC558 <b>Reg Expiry:</b> 27 Aug 2018			Engine				
WoF Expiry:	28 Jul 2020	Odometer:	26,166 Kms	Good No:	18507188	Oil leve	el	~		
VIN:	JSAAZC13S00106163	Next Service:	10,000kms	Service Histor	<b>y:</b> Yes	Smoke	& fumes	~		
						Perform	mance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	Noise			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							nt condition	~		
	D				D	Perform	mance	~		
Key:		-0		500-		Radiate	or / Hoses (visual)	~		
S = scratch D = dent							ission			
B = rust							Operation			
PT = paint defect								~		
C = crack						Clutch				~
P = pin dent * = decale							nts	~		
							Wheel bearings			
SC = stone chips W = significant scuffs						Brakes				
						Performance		~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand E	Brake	~		
						Tyres (lowest observed tread depth of tyres)				es)
						Left fro	Left front		3.5 mm	
						Right front		4 mm		mm
						Left rear		6 mm		mm
Conditions During Body Inspection: Dry						Right rear 6.5			.5	mm
						Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Susper	nsion performance	~		
						Steerin	ng performance	~		
							absorbers	~		
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments Cigarette holes on seats						Electrical / Accessories				
Seats	Cigarette	noles on seats				Head li	ights	~		
Carpets	Good					Tail lig	hts	~		
						Indicat	ors	~		
Panels	Good						oard warning lights	~		
Dashboa	rd Good					(front & rear)	~			
							w winder FL	~		
							w winder FR	~		
<u>General Comments</u>							w winder RL	~		
						Windo	w winder RR	~		
						Rear vi	ew mirrors	~		
							(basic test only)	~		
							sic test only)			~
									2	
Road Conditions During Test Drive: Dry							llocking	~		
Engine Timing Mechanisms							e locking	~		
Engine Timing Mechanism: Timing Chain							v. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Revers	ing camera	~		
Inspected by: Xinghui Lin Date: 07 Nov 2018										

I have read and understood this condition guide.

Name: .....

Signature: .....