

Basic Vehicle Condition Guide

Report ID: 18,507,600

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Created: 04 Oct 2018

Pass

1

~

/


N/A

Fail

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: Registration: HWQ390 Reg Expiry: 2007 21 Dec 2018 WoF Expiry: **Odometer:** 04 Oct 2019 **Good No:** 18507600 181,899 Kms VIN: KMHSH81DR7U20103 **Next Service:** 192000 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Greg Morgan

Kms:

Clutch			'
CV joints	~		
Wheel bearings	~		
rakes			
Performance	~		
Hand Brake	~		
yres (lowest observed treac	depth	of tyre	s)
Left front	5.0		mm
Right front	5.0		mm
Left rear	3.5		mm
Right rear	4.0		mm
Spare	Yes		
uspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
ir Conditioning / Heater			
Operation	~		
lectrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	VVV		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
Date: 02 Oct 201	18		
Signature:			

I have read and understood this condition guide.

Name:			