

Report ID: 51,719 Version: 1 Created: 10 Oct 2018

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:	DLS499	Reg Expiry:	02 Jul 2019	Engine			
WoF Expiry:	02 Oct 2019	Odometer:	162,268 Kms	Good No:	18507933	Oil level	~		
VIN:	6FPAAAJGAT6U93916	Next Service:	171000	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
			is can be analyed to		charge.	Coolant condition	~		
Kau	SC	$\sim$	S S		S	Performance	~		
<b>Key:</b> S = scratch		$\overline{(0)}$		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	AIP				HUS	Operation	~		
PT = paint def	ect N	1 1				Noise	~		
C = crack				$\prod_{i}$		Clutch			~
P = pin dent	SC S R dl			SL-	~HHs	CV joints	~		
* = decals SC S R SC = stone chips						Wheel bearings 🖌 🖌			
W = significant scuffs						Brakes			
		$\sim$	S	$\sim$		Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
RR Window intermittently working						Tyres (lowest observed tread depth of tyres)			
						Left front	6.0		mm
						Right front	4	.0	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mr		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Average						Electrical / Accessories			
Seats	//veluge					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	ard Good					Wipers (front & rear)	~		<b> </b>
						Window winder FL	~		+
General (	Comments					Window winder FR	~		
General Comments Minor knock in suspension						Window winder RL	~		+
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	<b>/</b>		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: SCOTT Date: 27 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....