

## **Basic Vehicle Condition Guide**

Report ID: 18,529,087


Version: 3

Created: 11 Oct 2019

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2017 Registration: KQA822 Reg Expiry: 31 Dec 2019 WoF Expiry: **Odometer:** 12 Jun 2020 56,815 Kms **Good No:** 18529087 VIN: MPATFS85JHT007836 Next Service: 66,800kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Both running boards damage Windscreen stone chips CVA

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

4WD

Interior Comments				
Seats	Good			
Carpets	Front floor mats missing			
Panels	Good			
Dashboard	Good			

## **General Comments**

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Ca Thach

	Pass	Fail	N/A
Engine	,		
Oil level	~		
Smoke & fumes	~		
Performance	\( \triangle \)		
Noise	~		
Cooling System	1		1
Coolant condition	~		
Performance	\( \times \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints	\( \times \)		
Wheel bearings	~		
Brakes	<u> </u>		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	9	9 m	
Right front	9		mm
Left rear	9 m		mm
Right rear	9		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			_
Operation	V_		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Min danning day FI			

Name: ..... Signature: .....

Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date:

1

1

1

1

11 Oct 2019

~

have road	and und	arctand th	nis conditio	ماننام