

Basic Vehicle Condition Guide

Report ID: 18,549,132


Version: 3

Created: 18 Oct 2019

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2006 Registration: LYL394 Reg Expiry: 10 Nov 2019 WoF Expiry: **Odometer: Good No:** 17 Dec 2019 84,272 Kms 18549132 VIN: 7AT0GK0CX18157808 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Remote part missing from the key

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

Rear wheel bearing noise

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

23 Sep 2019 Inspected by: Mathew Varghese Date:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
-		
V		
V		
		~
~		
	~	
V		
1/		
d denth	of tyre)
1		mm
		-
		mm
		mm
		mm
	Yes	
-		
~		
~		
	1	
~		
	1	
~		
~		
~		
~		
~		
~		
~		
V V		
~		
\(\times \)		
v		
\(\times \)		
V V V		
\(\times \) \(\t		
\(\times \) \(\t		
\(\times \) \(\t		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

I have read and understood this condition guide.

Name			