

# **Basic Vehicle Condition Guide**

Report ID: 18,550,859


Version:

Created: 19 Jun 2019

Make: Model: Toyota Landcruiser Prado **Body Style:** SUV Year: 2004 Registration: BUW433 Reg Expiry: 17 Aug 2019 WoF Expiry: **Odometer:** 20 Jul 2019 234,518 Kms **Good No:** 18550859 VIN: JTEBU29J100031886 Next Service: 233419 **Service History:** 

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



### **Body Inspection Comments**

Stone chips on the windscreen Front headlamps dull, RL door operation noisy Rear third row middle seat head rest missing Front wiper operation noisy, Aftermarket alloy fitted

Conditions During Body Inspection: Dry

### **Under Carriage & Under Bonnet Inspection Comments**

Engine oil seepage FR ball joint bush leak Transmission oil leak

Umpires surface rust ( minor )

| Interior  | Comments  |
|-----------|-----------|
| IIIICIIOI | Commencia |

| Seats     | Good                |
|-----------|---------------------|
| Carpets   | Average             |
| Panels    | Average             |
| Dashboard | crack on dash board |

## **General Comments**

One remote key not working out of two Engine mount weak

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Sudhin Ramachandran 19 Jun 2019 Inspected by: Date:

Name: .....

|   | Pass            | Fail    | N/A      |
|---|-----------------|---------|----------|
| Engine  |                 |         |          |
| Oil level                                     | ~               |         |          |
| Smoke & fumes                                 | ~               |         |          |
| Performance                                   | \( \times \)    |         |          |
| Noise   | ~               |         |          |
| Cooling System                                | •               |         |          |
| Coolant condition                             | ~               |         |          |
| Performance                                   | ~               |         |          |
| Radiator / Hoses (visual)                     | ~               |         |          |
| Transmission                                  | ı               | ı       | 1        |
| Operation                                     | ~               |         |          |
| Noise   | ~               |         |          |
| Clutch  |                 |         | ~        |
| CV joints                                     | ~               |         |          |
| Wheel bearings                                | ~               |         |          |
| Brakes  |                 |         | 1        |
| Performance                                   | ~               |         |          |
| Hand Brake                                    | ~               |         |          |
| Tyres (lowest observed tread                  | depth           | of tyre | es)      |
| Left front                                    |                 |         | mm       |
| Right front                                   | 9.5             |         | mm       |
| Left rear                                     | 9               |         | mm       |
| Right rear                                    | 9.5             |         | mm       |
| Spare   |                 | Yes     |          |
| Suspension                                    |                 | 103     |          |
| Suspension performance                        | ~               |         |          |
| Steering performance                          | ~               |         |          |
| Shock absorbers                               | ~               |         |          |
| Air Conditioning / Heater                     |                 |         |          |
| Operation                                     | ~               |         |          |
| Electrical / Accessories                      |                 |         |          |
| Head lights                                   | V               |         |          |
| Tail lights                                   | ~               |         |          |
| Indicators                                    | V               |         |          |
| Dashboard warning lights                      | ~               |         |          |
| Wipers (front & rear)                         |                 | ~       |          |
| Window winder FL                              | ~               |         |          |
| Window winder FR                              |                 |         |          |
| Window winder RL                              | \( \triangle \) |         |          |
| Window winder RR                              | 1               |         |          |
| Rear view mirrors                             | ~               |         |          |
|   | V               |         |          |
| Radio (basic test only)  CD (basic test only) |                 |         |          |
| <u> </u>                                      | 2               |         |          |
| Number of keys                                | 3               |         |          |
| Central locking                               | <i>V</i>        |         |          |
| Remote locking                                | <b>'</b>        |         |          |
| Sat. Nav. (basic test only)                   |                 |         | <b>'</b> |
| Reversing camera                              |                 |         |          |

Signature: .....