

Report ID: 18,558,795


Version:

Created: 19 Sep 2018

Make:	Suzuki	Model:	MR	Body Style:	Hatchback
Year:	2002	Registration:	DGE53	Reg Expiry:	17 Oct 2018
WoF Expiry:	14 Jun 2019	Odometer:	53,799 Kms	Good No:	18558795
VIN:	7A8GKG00706112331	Next Service:		Service History	/: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper misaligned

Conditions During Body Inspection: Dr	Conditions	During E	ody Ins	pection:	Drv
---------------------------------------	------------	----------	---------	----------	-----

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 19 Sep 2018 Inspected by: Mathew Varghese

Name:

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation	V V V V V V V V V V V V V V V V V V V		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation	<i>V</i>		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation	<i>V</i>		
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation	<i>V</i>		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation	<i>V</i>		
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation			
Performance Radiator / Hoses (visual) Transmission Operation			
Radiator / Hoses (visual) Transmission Operation	<i>V V</i>		
Transmission Operation	V		
Operation			
	V		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	1	.6	mm
Right front	1	.6	mm
Left rear	į	5	mm
Right rear		5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	\(\times \) \(\t		
Window winder RL	~		
Window winder RR	•		
Rear view mirrors	'		
Radio (basic test only)	'		
CD (basic test only)	'		
Number of keys	1	ı	
Central locking	•		
Remote locking			~
Sat. Nav. (basic test only)			~
Reversing camera			'

Signature: