

Basic Vehicle Condition Guide

Report ID: 18,558,977


Version: 3

Created: 17 Oct 2018

Make: Model: Mitsubishi Outlander **Body Style:** SUV Year: Registration: Reg Expiry: 2014 HFQ27 09 Oct 2018 WoF Expiry: **Odometer:** 09 Jan 2019 **Good No:** 230,028 Kms 18558977 VIN: JMFXLGF6WDZ00138 **Next Service:** 245000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips front screen. Scratch left front door mirror. Scratch mark right hand taillight lens.

Pin dents in some of the door jams. Interior roof right sun visor mirror broken.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Drivers sunvisor mirror cracked. Glove box stuck.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 05 Oct 2018

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
•	•	
~		
~		
depth	of tyre	es)
5	.0	mm
5.0		mm
5	.0	mm
5.0		mm
	Yes	
•		
~		
~		
~		
	•	_
~		
~		
V V V		
V V V		
V V V		
V V V V V V		
V V V V V V		
\(\times \) \(\t		
V V V V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V V		
V V V V V V V		
	ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン い い い い い	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: