

I have read and understood this condition guide.

Report ID: 18,559,478 Version: 4 22 Feb 2019 Created:

Signature:

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011	Registration:	HQY761	Reg Expiry:	11 Jan 2019	Engine		1	•
WoF Expiry:	21 Sep 2019	Odometer:	147,976 Kms	Good No:	18559478	Oil level	~		
VIN:	7AT0GF0BX14017494	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	or an additional o	narge.	Coolant condition	~		
	S D		S S P		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust				710	S D PT	Operation	~		
PT = paint def	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	s de				74116	CV joints	~		
* = decals		1		10	ED SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S W		S S		S	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	r		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front 7 m				
						Right front	5	7	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	<u> </u>	5	mm
Conditions During Body inspection. Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	
						Operation		V	
Interior Comments						Electrical / Accessories	1	1	
Seats	Good					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	coin tray d	amage				Wipers (front & rear)	~		
Dashboa	rd	amaye				Window winder FL	~		
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
AC not wor	king					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	I	
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1	1	L
Inspected by: Bobby Zhong Date: 22 Feb 2019									

Name: