

Report ID: 18,559,990 Version: 1 Created: 13 Sep 2018

Make:	Subaru	Model:	Logocy	Body Style:	Wagon		Pass	Fail	N/A
Year:	2000	Registration:	Legacy ZN3871	Reg Expiry:	20 Feb 2019	Engine	1 435	1 un	
WoF Expiry:		Odometer:		Good No:		Oil level			<u> </u>
VIN:		Next Service:	234,462 Kms	Service Histor	18559990	Smoke & fumes	~		
V IIN.	JF1BH9KJ41G026702	Next Service.		Service mistor	y: No		~		──
Note: This re	port is not a warranty					Performance	~		
	a guide only. Consid					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		<u> </u>
Key:	P SC W		S PT P P SC	W		Performance	~		<u> </u>
S = scratch	~	\sim (O)		5(O)-	\checkmark	Radiator / Hoses (visual)	~		
D = dent				100	S PT	Transmission			
R = rust	SDCSC P				HILL	Operation	~		
PT = paint def	ect N	1				Noise	~		
C = crack					PT SC	Clutch	~		
P = pin dent	sc dl				~HHL8	CV joints	~		
* = decals		a o		70	SPT SPT	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significan	D SC W		SDP P	W	SC	Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
LH low and high beam not going. Clearcoat is coming off vehicle. Garnish on tailgate is cracked. Moisture in						Tyres (lowest observed tread depth of tyres)			es)
RH reversing lamp. Scratches on RH A pillar. Stonechips on windscreen.						Left front 4			mm
						Right front	4	1	mm
						Left rear	1	5	mm
Conditions During Body Inspection: Dry					Right rear	ļ	5	mm	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear differe	ntial has oil seepage.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights		~	
	Average					Tail lights	~		
Carpets	/ treage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		1
Dashboa	ird					Window winder FL	~		1
						Window winder FR	~		1
General Comments					Window winder RL	~		1	
Gearlever has excessive movement. Clutch has wear.						Window winder RR	~		1
Drives ok.						Rear view mirrors	~		1
						Radio (basic test only)	~		+
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Drv						Central locking	~		1
Road Conditions During Test Drive: Dry					Remote locking	~		+	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	·		~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1		
Inspecte	d by: Roger King					Date: 13 Sep 20	18		
	and understand th		uido Nomo			Cignosturo			

I have read and understood this condition guide.

Name:

Signature: