

Report ID: 18,560,311 Version: 1 13 Sep 2018 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2009	Registration:	EYO646	Reg Expiry:	27 Oct 2018	Engine			·
WoF Expiry:	17 Apr 2019	Odometer:	222,086 Kms	Good No:	18560311	Oil level	~		
VIN:	VSKCVND40A0321652	Next Service:	218950	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-	S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC						Operation	Operation 🖌		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				74 <u>11</u>	CV joints	~		
* = decals	sc 916			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan			S S			Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front			mm	
						Right front	4		mm
						Left rear	4		mm
Conditions During Body Inspection: Wet						Right rear	4 mm		mm
Contractions During Dody inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
Shock							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	, the age					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
-	ning Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 13 Sep 2018									
Inspected by: Stuart Melbourne Date: 13 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....