

Report ID: 18,560,492 Version: 1 24 Oct 2018 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:	GBP836	Reg Expiry:	14 Jun 2019	Engine			
WoF Expiry:	23 Jul 2019	Odometer:	181,913 Kms	Good No:	18560492	Oil level	~		
VIN:	MNTVCUD40A001986	Next Service:	185000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC SD SD						Operation 🖌			
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	MIE			The second	ELD'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	l depth	of tyre	es)
									mm
						Right front	3		mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						 Right rear	5.0		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Minor noise	e in front suspension					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Dry						Central locking			
						Remote locking	· ·		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-								
Inspected by: Dion Mair Date: 14 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: