

Report ID: 18,561,267 Version: 3 22 Dec 2018 Created:

Make:	Dodge	Model:	Journey	Body Style:	SUV		Pass	Fail	N/A
Year:	2010	Registration:	HLQ540	Reg Expiry:	02 Jul 2019	Engine			L
WoF Expiry:	08 Sep 2019	Odometer:	170,800 Kms	Good No:	18561267	Oil level	~		
VIN:	3D4P56FD8AT184088	Next Service:	180,214	Service Histor	y: No	Smoke & fumes	~		
			·		-	Performance	~		
	port is not a warranty		6	Danta have a st	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:	SD S	-0	S S			Radiator / Hoses (visual)	~		
S = scratch						Transmission	<u>, , , , , , , , , , , , , , , , , , , </u>		
D = dent	s sc			The	EID S	Operation	~		
R = rust PT = paint defe				r In	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	SDSC PIE			AL.	EIPE	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs DRW S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disr		Hand Brake	~		
Body Insp	pection Comments	1010.3011		indy not be disp	ayea in the diagram		-	oftyre	() ()
						Tyres (lowest observed tread depth of tyres) Left front 3			
						Right front			mm
						Left rear	3		mm mm
			_				5		-
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments							Spare Yes		
	inage a onder bor	iner inspectie	comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		L
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
					_	Window winder FL	~		
Concrol	Comments					Window winder FR	~		
General	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		Ĺ
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Th	ning Machanism	T:	Chain			Remote locking	~		
-	ming Mechanism:	Timing (IZ .		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Ca Thach Date: 22 Dec 2018									

Name: